



Van Horn Aviation, L.L.C.
1510 W. Drake Drive
Tempe, Arizona 85283

FAA APPROVED

ROTORCRAFT FLIGHT MANUAL SUPPLEMENT

For

VHA TAIL ROTOR BLADES

Installed On

TAMARACK UH-1F, TH-1F HELICOPTERS

REGISTRATION No. _____

SERIAL No. _____

This supplement must be attached to the T.O. 1H-1(U)F-1, TH-1F, UH-1F and UH-1P Flight Manual when the Van Horn Aviation **VHA Tail Rotor Blades** are installed in accordance with STC No. SR02051LA.

The information contained herein supplements or supersedes the information in the Flight Manual only in those areas listed herein. For limitations, procedures, and performance data not contained in this supplement, consult the Flight Manual and applicable Flight Manual Supplements.

FAA Approved:

A handwritten signature in blue ink, appearing to read 'S. Kemp-Harbin', is written over a horizontal line.

Manager, Flight Test Branch, ANM-160L
Federal Aviation Administration
Los Angeles Aircraft Certification Office
Transport Airplane Directorate

Date:

A handwritten date 'March 2, 2017' in blue ink is written over a horizontal line.


Original approval date: 4/17/2008



Van Horn Aviation, L.L.C.
 1510 W. Drake Drive
 Tempe, Arizona 85283

RFM Supplement to the
 Tamarack UH-1F, TH-1F
 Flight Manual,
 T.O. 1H-1(U)F-1
 STC No. SR02051LA

LOG OF PAGES

Rev. No.	Page No.	Page Rev.	Description	FAA Approval
0	1 2 3 4 5 6	0 0 0 0 0 0	Original issue of complete supplement.	/s/ <u>Seyed-Youssef Hashemi</u> Mgr, Flt Test Br, ANM-160L FAA, Los Angeles ACO Transport Airplane Directorate Date: <u>4/17/2008</u>
1	1* 2* 3* 4* 5* 6*	1 1 1 1 1 1	Revised supplement to incorporate Van Horn Aviation's new address.	/s/ <u>Seyed-Youssef Hashemi</u> Mgr, Flt Test Br, ANM-160L FAA, Los Angeles ACO Transport Airplane Directorate Date: <u>07/02/2012</u>
2	1* 2* 3* 4* 5* 6*	2 2 2 2 2 2	Revised supplement to remove tail rotor part number.	 Mgr, Flt Test Br, ANM-160L FAA, Los Angeles ACO Transport Airplane Directorate Date: <u>March 2, 2017</u>

Revised pages marked with "*" symbol.

NOTE

Revised text is indicated by a black vertical line.
 Insert latest revision pages; dispose of superceded pages.



Van Horn Aviation, L.L.C.
1510 W. Drake Drive
Tempe, Arizona 85283

RFM Supplement to the
Tamarack UH-1F, TH-1F
Flight Manual,
T.O. 1H-1(U)F-1
STC No. SR02051LA

TABLE OF CONTENTS

<u>TITLE</u>	<u>PAGE NO.</u>
Section I, Description.....	4
Section II, Normal Procedures.....	4
Section III, Emergency Procedures.....	5
Section IV, Auxiliary Equipment.....	5
Section V, Operating Limitations.....	5
Section VI, Flight Characteristics.....	5
Section VII, Systems Operation.....	5
Section VIII, Crew Duties.....	6
Section IX, All Weather Operation.....	6
Appendix I, Performance Data.....	6



Van Horn Aviation, L.L.C.
1510 W. Drake Drive
Tempe, Arizona 85283

RFM Supplement to the
Tamarack UH-1F, TH-1F
Flight Manual,
T.O. 1H-1(U)F-1
STC No. SR02051LA

SECTION I DESCRIPTION

TAIL ROTOR

The tail rotor is a two-bladed, semi-rigid, delta hinged type employing preconing and underslinging. Each blade is connected to a common yoke by a grip and pitch change bearings. The blade and yoke assembly is mounted on the tail rotor shaft by a delta-hinge trunnion to minimize rotor flapping. Blade pitch is altered by movement of the tail rotor control pedals to control or maintain heading. This blade pitch change provides anti-torque control. Power to drive the tail rotor is supplied from a take-off on the lower aft section of the main rotor transmission.

TAIL ROTOR BLADES

The VHA 2042200-101/-103 tail rotor blade is an all composite blade employing an advanced high efficient airfoil. The blade length is the same as the existing production blade, but the chord has been increased by .80 inches. Erosion protection is provided by a full span stainless steel abrasion strip adhesively bonded to the leading edge. Stainless steel bushings are pressed into the inboard end, which react to the attachment bolt loads. The blade is constructed primarily of carbon/epoxy unidirectional tape. The grip plates, tip closure and root closure are fabricated from fiberglass/epoxy fabric. The blades are statically balanced at the factory using a brass balance weight threaded into the tip closure. The interior of the blade is filled with closed cell rigid foam.

SECTION II NORMAL PROCEDURES

ENGINE RUNUP

4.(a.)(4) Tail Rotor Controls – CHECK (Move pedals slowly to verify that Tail Rotor Pitch change can be make, “BOOST OFF”, and moves smoothly without vibration.

NOTE

Without hydraulic boost and with the VHA 2042200-101/-103 tail rotor blades installed, a significantly higher force will be required to move the left pedal forward than to move the right pedal forward. However, little or no pedal force is required to maintain pedal position.



Van Horn Aviation, L.L.C.
1510 W. Drake Drive
Tempe, Arizona 85283

RFM Supplement to the
Tamarack UH-1F, TH-1F
Flight Manual,
T.O. 1H-1(U)F-1
STC No. SR02051LA

SECTION III EMERGENCY PROCEDURES

HYDRAULIC POWER SYSTEM FAILURE

NOTE

Without hydraulic boost and with the VHA 2042200-101/-103 tail rotor blades installed, a significantly higher force will be required to move the left pedal forward than to move the right pedal forward. However, little or no pedal force is required to maintain pedal position.

SECTION IV AUXILIARY EQUIPMENT

No change.

SECTION V OPERATING LIMITATIONS

No change.

SECTION VI FLIGHT CHARACTERISTICS

BOOST OFF CHARACTERISTICS

NOTE

Without hydraulic boost and with the VHA 2042200-101/-103 tail rotor blades installed, a significantly higher force will be required to move the left pedal forward than to move the right pedal forward. However, little or no pedal force is required to maintain pedal position.

SECTION VII SYSTEMS OPERATION

No change.



Van Horn Aviation, L.L.C.
1510 W. Drake Drive
Tempe, Arizona 85283

RFM Supplement to the
Tamarack UH-1F, TH-1F
Flight Manual,
T.O. 1H-1(U)F-1
STC No. SR02051LA

SECTION VIII CREW DUTIES

No change.

SECTION IX ALL WEATHER OPERATION

BOOST-OFF OPERATIONS

NOTE

| Without hydraulic boost and with the VHA 2042200-101/-103 tail rotor blades installed, a significantly higher force will be required to move the left pedal forward than to move the right pedal forward. However, little or no pedal force is required to maintain pedal position.

APPENDIX I PERFORMANCE DATA

No change.