

**Government of India  
Civil Aviation Department  
Office Of The  
Directorate General of Civil Aviation  
Aircraft Engineering Directorate  
Opposite Safdarjung Airport  
New Delhi - 110 003**



भारत सरकार  
नागर विमानन विभाग  
महानिदेशक नागर विमानन का कार्यालय  
सफदरजंग एयरपोर्ट के सामने  
नई दिल्ली - ११० ००३

**Phone:-91-011-2462 3211  
E mail: indranil.dgca@nic.in**

**Reference  
No.:**

**संख्या : 07-17/2018-AED  
दिनांक : 25 /05/2018**

**Dated:**

✓ Van Horn Aviation, LLC,  
1510W. Drake Drive,  
Temp, Arizona (AZ 85283)

(Kind Attn: Mr. Dean Rosenlof)

**Sub: Type Acceptance of FAA Supplemental Type Certificate STC SR02249LA for installation of tail rotor blade on Bell Helicopters Model 206L-4.**

References:

- I. FAA letter ref. no. 790-18-4053, dated 23.04.2018.
- II. Letter of Intent from Indian operator M/s Dhillon Aviation Pvt Ltd letter dated 02.04.2018.

Sir,

Reference may please be made to the above referred letters and subsequent correspondence this office had on the subject matter.

The certification documents pertaining to installation of tail rotor blade on Bell Helicopters Model 206L-4 have been examined and are considered satisfactory. Based on the information, documents and clarification provided, it is stated that the modification of tail rotor blade installation certified vide FAA STC SR02249LA dated 16/07/2012 on Bell Helicopters Model 206L-4 is considered acceptable to DGCA from design view point subject to the following conditions;

1. The installation must conform to type design change data as specified in the FAA STC mentioned above.
2. Limitations, conditions and procedures specified in the STC, approved RFM shall be strictly adhered to;
3. The Indian operator shall provide to AED quarterly feedback/data on the tail rotor blade installation pertaining to all faults/malfunctions/service difficulties/repairs/part replacements, etc.

This letter of STC acceptance is issued under the provisions of Rule 49G of the Aircraft Rules 1937 with the approval of the competent authority and shall remain in force until cancelled, superseded or revoked by the DGCA, India

Yours faithfully



(Indranil Chakraborty)  
Director (AED)

for Director General of Civil Aviation

Copy to:

1. DAW, DGCA Head Quarters, New Delhi – 110003.
2. FAA, Compliance & Airworthiness Division, Los Angeles ACO Branch, 3960 Paramount Boulevard. Suite 100 Lakewood, California 90712-4137.  
(Kind Attn: Mr. Kevin Hull, Manager, Los Angeles ACO Branch)
3. M/s Dhillon Aviation Pvt Ltd. A-883/C, Sushant Lok-I, Gurgaon-122001.  
(Kind Attn: Jaymalya Sengupta, Quality Manager).