



READ ME FIRST!

Van Horn Aviation UH-1 Tail Rotor Blades

You are about to install Van Horn Aviation aftermarket composite rotor blades. These blades are designed to be different than the OEM blades. They may require PILOT RE-ACQUAINTANCE.

Download the appropriate Instructions for Continued Airworthiness (ICA) and Flight Manual Supplement (FMS) for your helicopter from vanhornaviation.com/documents.

Model	Instructions for Continued Airworthiness	Rotorcraft Flight Manual Supplement
Arrow Falcon UH-1H	VMM-UH1-302 ICA	204T-FMS-902
AST UH-1F	VMM-UH1-309 ICA	204T-FMS-909
Rotorcraft Dev. Corp (Garlick) UH-1B	VMM-UH1-312 ICA	204T-FMS-912
Rotorcraft Dev. Corp (Garlick) UH-1H	VMM-UH1-301 ICA	204T-FMS-901
Rotorcraft Dev. Corp (Garlick) UH-1F, TH-1F, UH-1P	VMM-UH1-308 ICA	204T-FMS-908
Hagglund UH-1H	VMM-UH1-303 ICA	204T-FMS-903
International Helicopters UH-1B	VMM-UH1-317 ICA	204T-FMS-917
Northwest UH-1H	VMM-UH1-304 ICA	204T-FMS-904
Overseas Aircraft Support UH-1B	VMM-UH1-315 ICA	204T-FMS-915
Robinson Air Crane UH-1F, TH-1F, UH-1P	VMM-UH1-311 ICA	204T-FMS-911
San Joaquin Helicopters UH-1B	VMM-UH1-316 ICA	204T-FMS-916
Richard's HeavyLift (S.M.&T.) UH-1B	VMM-UH1-313 ICA	204T-FMS-913
Richard's HeavyLift (S.M.&T.) UH-1H	VMM-UH1-305 ICA	204T-FMS-905
Southwest Florida Aviation UH-1B	VMM-UH1-314 ICA	204T-FMS-914
Southwest Florida Aviation UH-1H	VMM-UH1-306 ICA	204T-FMS-906
Tamarack UH-1F	VMM-UH1-310 ICA	204T-FMS-910
Tamarack UH-1H	VMM-UH1-318 ICA	204T-FMS-918
Overseas Aircraft Support (Williams) UH-1H	VMM-UH1-307 ICA	204T-FMS-907

QUESTIONS? Visit www.vanhornaviation.com or call 1-480-483-4202.

WARRANTY INFORMATION

Van Horn Aviation warrants this product to be free from defects in workmanship and materials, under normal use and conditions, for a period of three (3) years from date of manufacture or 1,500 flight hours (whichever comes first). This warranty excludes bushing replacement and damage due to erosion or object strike.