

FAA APPROVED MODEL LIST (AML) NO. SR02249LA
VAN HORN AVIATION, L.L.C.
INSTALLATION OF TAIL ROTOR BLADES

STC Original Issue Date: August 10, 2009
 AML Original Issue Date: June 4, 2010

ITEM	AIRCRAFT MAKE	AIRCRAFT MODEL	ORIGINAL TYPE CERTIFICATE NUMBER	CERTIFICATION BASIS	CONTROLLED DOCUMENTS		AML AMENDMENT DATE/ REISSUED DATE
					NUMBER	REVISION NO. & DATE	
1	Bell Helicopter Textron	206B	H2SW	As Noted on STC SR02249LA	Master Document List (MDL) 206-MDL-001	Rev. W 6/10/2020 ¹	06/07/2011 03/12/2021
					Instructions For Continued Airworthiness (ICA) VMM-206B-301 VMM-206-501	Rev. J, 9/15/14 ^{2,4} Rev. N/C 01/28/21 ²	
					Airworthiness Limitation Section (ALS)	05/19/14 ^{3,4} 03/12/2021 ³	
2	Bell Helicopter Textron	206L	H2SW	As Noted on STC SR02249LA	Master Document List (MDL) 206-MDL-001	Rev. W 6/10/2020 ¹	06/07/2011 03/12/2021
					Instructions For Continued Airworthiness (ICA) VMM-206L-303 VMM-206-501	Rev. H, 9/15/14 ^{2,4} Rev. N/C 01/28/21 ²	
					Airworthiness Limitation Section (ALS)	07/30/13 ^{3,4} 03/12/2021 ³	
3	Bell Helicopter Textron	206L-1	H2SW	As Noted on STC SR02249LA	Master Document List (MDL) 206-MDL-001	Rev. W, 6/10/2020 ¹	12/15/2011 03/12/2021
					Instructions For Continued Airworthiness (ICA) VMM-206L1-305 VMM-206-501	Rev. I, 9/15/14 ^{2,4} Rev. N/C, 01/28/21 ²	
					Airworthiness Limitation Section (ALS)	10/18/17 ^{3,4} 03/12/2021 ³	
4	Bell Helicopter Textron	206L-3	H2SW	As Noted on STC SR02249LA	Master Document List (MDL) 206-MDL-001	Rev. W, 6/10/2020 ¹	12/15/2011 03/12/2021
					Instructions For Continued Airworthiness (ICA) VMM-206L3-307 VMM-206-501	Rev. I, 9/15/14 ^{2,4} Rev. N/C, 01/28/21 ²	
					Airworthiness Limitation Section (ALS)	10/18/13 ^{3,4} 03/12/2021 ³	
5	Bell Helicopter Textron	206L-4	H2SW	As Noted on STC SR02249LA	Master Document List (MDL) 206-MDL-001	Rev. W, 6/10/2020 ¹	12/15/2011 03/12/2021
					Instructions For Continued Airworthiness (ICA) VMM-206L4-309 VMM-206-501	Rev. I, 9/15/14 ^{2,4} Rev. N/C, 01/28/21 ²	
					Airworthiness Limitation Section (ALS)	10/18/13 ^{3,4} 03/12/2021 ³	

FAA APPROVED MODEL LIST (AML) NO. SR02249LA
VAN HORN AVIATION, L.L.C.
INSTALLATION OF TAIL ROTOR BLADES

STC Original Issue Date: August 10, 2009
 AML Original Issue Date: June 4, 2010

6	Arrow Falcon Exporters, Inc.	OH-58A+ OH-58C	H22NM	As Noted on STC SR02249LA	Master Document List (MDL) 206-MDL-001	Rev. W, 6/10/2020 ¹	06/07/2011 03/12/2021
					Instructions For Continued Airworthiness (ICA) VMM- OH58-311 VMM-206-501	Rev. E, 9/15/14 ^{2,4} Rev. N/C, 01/28/21 ²	
					Airworthiness Limitation Section (ALS)	07/30/13 ^{3,4} 03/12/2021 ³	
7	Rotorcraft Development Corporation	OH-58A+ OH-58C	R00006DE	As Noted on STC SR02249LA	Master Document List (MDL) 206-MDL-001	Rev. W, 6/10/2020 ¹	06/07/2011 03/12/2021
					Instructions For Continued Airworthiness (ICA) VMM-OH58-313 VMM-206-501	Rev. E, 9/15/14 ^{2,4} Rev. N/C, 01/28/21 ²	
					Airworthiness Limitation Section (ALS)	07/30/13 ^{3,4} 03/12/2021 ³	
8	Blair Helicopter Services, Inc.	OH-58A+ OH-58C	R00002LA	As Noted on STC SR02249LA	Master Document List (MDL) 206-MDL-001	Rev. W, 6/10/2020 ¹	06/07/2011 03/12/2021
					Instructions For Continued Airworthiness (ICA) VMM-OH58-315 VMM-206-501	Rev. E, 9/15/14 ^{2,4} Rev. N/C, 01/28/21 ²	
					Airworthiness Limitation Section (ALS)	07/30/13 ^{3,4} 03/12/2021 ³	

Notes:

¹ or later FAA approved revisions.

² or later FAA accepted revisions. ICA must be made available to the operator at the time of installation.

³ or later FAA approved revisions effective on the date of initial airworthiness certification.

⁴ ICA document applies to part number 2062200-101/-301 only.

FAA Approved _____ Date: 03/12/2021

Maureen Moreland
 Aviation Safety
 Manager, Airframe Section
 Los Angeles ACO Branch